


# 'SNAP-SEAL' Triple Crimp Tool

## For RG6, RG59, ('F' & BNC) & RCA

### Instructions

C2004 comes with 3 interchangeable plungers for 'F', BNC and RCA compression connectors

1. Insert the correct plunger into the tool's holder, then insert the stripped cable into the connector, make sure the cable is full inserted
2. Place the connector with cable into the tools compression chamber.
3. Squeeze handles. When crimping with BNC fitting DO NOT close handles completely
4. Remove the crimped connector from the tool.



Compressed distance for 'F' connector	Compressed distance for BNC connector	Compressed distance for RCA connector
20.3+/-0.20mm	33.9+/-0.20mm	31.6+/-0.20mm



[www.sacelectronics.co.uk](http://www.sacelectronics.co.uk)